

09/692,297

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,847,926 B1
DATED : January 25, 2005
INVENTOR(S) : Peter Ballam

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 18.

Line 65, should read -- circuit comprising the steps of --


Line 66, should read -- for a bi-directional pin of said model, applying signals to said --

Column 20.

Line 10, should read -- signal on said bi-directional pin will be super imposed over the --

Signed and Sealed this

Seventeenth Day of May, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office